

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Alliance Technical Group, LLC - Newark

Project: NJ Waste Water PT Client Sample ID: WP0925-PT-COND-WP

Lab Sample ID: Q3019-08

Date Collected: 09/02/25 10:00

Date Received: 09/04/25 SDG No.: Q3019 Matrix: Water

% Solid: 0

Parameter	Conc. Qu	a. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Conductance	794	1 0.99	2.00	umho/cm		09/12/25 13:4	5 120.1

Comments: Conductance Result is Corrected to 25°C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits