

Report of Analysis

Client:	VERINA CONSULTING GROUP, LLC	Date Collected:	09/04/25 10:38
Project:	Rotor Clip NJ WTD - 2025	Date Received:	09/04/25
Client Sample ID:	WATER-TREATMENT DISCHARGE	SDG No.:	Q3020
Lab Sample ID:	Q3020-01	Matrix:	WATER
		% Solid:	0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Ammonia as N	0.30		1	0.030	0.10	mg/L	09/08/25 08:05	09/08/25 12:03	SM 4500-NH3 B plus G-21
BOD5	51.0		1	0.20	2.00	mg/L		09/05/25 09:50	SM 5210 B-16
COD	61.3		1	1.50	10.0	mg/L		09/08/25 13:37	SM 5220 D-11
Residual Chlorine	0.035	HJ	1	0.023	0.10	mg/L		09/05/25 10:27	SM 4500-Cl G-11
TSS	16.2		1	1.00	4.00	mg/L		09/08/25 14:00	SM 2540 D-20

Comments: _____

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N = Spiked sample recovery not within control limits