

 $284 \; Sheffield \; Street, \; Mountainside, \; New \; Jersey \; 07092, \; Phone \; : \; 908 \; 789 \; 8900, \\$

Fax: 908 789 8922

Report of Analysis

Client: VERINA CONSULTING GROUP, LLC Date Collected: 09/04/25 10:33

Project: Rotor Clip NJ WTD - 2025 Date Received: 09/04/25

Client Sample ID: WATER-TREATMENT DISCHARGE SDG No.: Q3020

Lab Sample ID: Q3020-02 Matrix: WATER

% Solid: 0

Parameter	Conc. Qua	a. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Oil and Grease	10.7	1 0.29	5.00	mg/L		09/05/25 10:00	1664A

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits