

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Parkway Generation Operating LLC Date Collected: 09/04/25 09:20 Project: Linden Generating Station - LRSA Date Received: 09/04/25 Client Sample ID: **DSN002** SDG No.: Q3025 Lab Sample ID: Q3025-02 Matrix: WATER

% Solid: 0

Parameter	Conc. Qu	a. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Field pH	6.99	1 0	0	рН		09/04/25 09:2	26 SM4500-H B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits