

CLIENT INFORMATION

REPORT TO BE SENT TO:

COMPANY: Zuccaro Inc.

ADDRESS: 3 Coal Ave

CITY: Morristown STATE: NJ ZIP:

ATTENTION: Sal Zuccaro

PHONE:

FAX:

CLIENT PROJECT INFORMATION

PROJECT NAME: 3 Coal Ave, Morristown, NJ

PROJECT NO.: LOCATION:

PROJECT MANAGER:

e-mail:

PHONE:

FAX:

CLIENT BILLING INFORMATION

BILL TO:

PO#:

ADDRESS:

CITY: Summit

STATE:

ZIP:

ATTENTION:

PHONE:

ANALYSIS

DATA TURNAROUND INFORMATION

FAX (RUSH) _____ DAYS*

HARDCOPY (DATA PACKAGE): _____ DAYS*

EDD: _____ DAYS*

*TO BE APPROVED BY CHEMTECH

STANDARD HARDCOPY TURNAROUND TIME IS 10 BUSINESS

DATA DELIVERABLE INFORMATION

☐ Level 1 (Results Only) ☐ Level 4 (QC + Full Raw Data)

☐ Level 2 (Results + QC) ☐ NJ Reduced ☐ US EPA CLP

☐ Level 3 (Results + QC) ☐ NYS ASP A ☐ NYS ASP B

+ Raw Data ☐ Other _____

☐ EDD FORMAT _____

Metals TCL-TCL
SVOC-TCL BNA-20
PCB
TCL BNA
Mercury
TCL VOA
VOC-TCL VOA-10

PRESERVATIVES

COMMENTS

← Specify Preservatives

A-HCl D-NaOH
B-HNO3 E-ICE
C-H2SO4 F-OTHER

ALLIANCE SAMPLE ID	PROJECT SAMPLE IDENTIFICATION	SAMPLE MATRIX	SAMPLE TYPE		SAMPLE COLLECTION		# OF BOTTLES										
			COMP	GRAB	DATE	TIME		1	2	3	4	5	6	7	8	9	
1.	Soil pile #1	SOL	X		9.5.25	11:14	5	X	X	X	X	X					
2.	I	I		X	I	11:16	5						X	X			
3.	Soil pile #2	I	X		I	11:36	5	X	X	X	X	X					
4.	I	I		X	I	11:40	5						X	X			
5.																	
6.																	
7.																	
8.																	
9.																	
10.																	

SAMPLE CUSTODY MUST BE DOCUMENTED BELOW EACH TIME SAMPLES CHANGE POSSESSION INCLUDING COURIER DELIVERY

RELINQUISHED BY SAMPLER:	DATE/TIME: 12:06	RECEIVED BY:	Conditions of bottles or coolers at receipt: ☐ COMPLIANT ☒ NON COMPLIANT	COOLER TEMP: 4.2°C
1. [Signature]	9.5.2025	1. [Signature]	Comments: Equal volume of soil used, 5:1 composite	
RELINQUISHED BY SAMPLER:	DATE/TIME:	RECEIVED BY:	* Soil pile #1 - 24x16x7 = measurement *	
2. [Signature]		2. [Signature]	* Soil pile #2 - 24x22x7 = measurement *	
RELINQUISHED BY SAMPLER:	DATE/TIME: 12:36	RECEIVED BY:	Page 1 of 1	CLIENT: ☐ Hand Delivered ☐ Other
3. [Signature]	9.5.2025	3. [Signature]		Shipment Complete ☐ YES ☐ NO

CHEMTECH

Environmental Laboratory

www.chemtech.net | EMAIL: PM@chemtech.net

Project Name: 3 COOL AVE,
MORRISTOWN, N.J.

Service Order #:

Work Order #:

Labor WBS #:

Facility/Site:

Site Address: 3 COOL AVE
MORRISTOWN, NJ.

Chemtech Order ID:

Sampler Name: Lawrence Carter

Client Project Coordinator & Phone:

Page #: 1 of 1

Date: 9.5.2025

Arrive Time: 10:38

Depart Time: 12:06

Waste Stream (circle one): drum / roll-off / soil pile / in-situ / linear construction / frac-tank

Sample Matrices (circle all that apply): Water / Solid / NAPL / Concrete / Wipe

Collection Depths:

Temp (range):

°C

PID Readings (range):

Dimensions/CY:

soil pile #1 / soil pile #2
100cy / 136cy

PPM

Odor: Y N


Color: Y N

Sample Description: Brown wet soil, rocks, GRASS.

Field Observations: SAMPLED, soil pile #1, soil pile #2

Grid/Area Composite Map:

QA Control # A3041134



Sampler Signature: L. Carter

9.5.2025

Supervisor Review/Date:

Client Signature:

Date/Time Arrived at Lab: