

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900, Fax: 908 789 8922

**Report of Analysis** 

Client:	PSEG	Date Collected:	09/08/25
Project:	Halladay MGP Site	Date Received:	09/08/25
Client Sample ID:	DNAPL	SDG No.:	Q3045
Lab Sample ID:	Q3045-06	Matrix:	TCLP
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-47-3	Chromium	26.1	1 0.011	0.050	mg/L	09/09/25 12:30	09/09/25 14:54	6010D	SW3050

Color Before: Colorless Clarity Before: Clear Texture: Color After: Colorless Clarity After: Clear Artifacts:

TCLPMetals Group2 Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits