

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: CHA Companies, Inc. Date Collected: 09/09/25 09:22 Project: NYSOMH Emergency Service Date Received: 09/09/25 Client Sample ID: B2-W16-RM4065-Eyewash SDG No.: Q3061 Lab Sample ID: Q3061-05 Matrix: Water % Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Residual Chlorine	0.023	HU	1	0.023	0.10	mg/L		09/10/25 11:55	SM 4500-C1 G-11
Turbidity	0.40	J	1	0.15	1.00	NTU		09/10/25 13:20	SM 2130 B-20

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits