



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Initial and Continuing Calibration Verification

Client: CHA Companies, Inc.

SDG No.: Q3061

Project: NYSOMH Emergency Service

RunNo.: LB137137

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Residual Chlorine	mg/L	0.429	0.4	107	90-110	09/10/2025
Sample ID: CCV1 Residual Chlorine	mg/L	0.398	0.4	100	90-110	09/10/2025
Sample ID: CCV2 Residual Chlorine	mg/L	0.398	0.4	100	90-110	09/10/2025
Sample ID: CCV3 Residual Chlorine	mg/L	0.408	0.4	102	90-110	09/10/2025

Initial and Continuing Calibration Verification

Client: CHA Companies, Inc.

SDG No.: Q3061

Project: NYSOMH Emergency Service

RunNo.: LB137138

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID:	ICV						
Turbidity		NTU	10.564	10	106	90-110	09/10/2025
Sample ID:	CCV1						
Turbidity		NTU	10.189	10	102	90-110	09/10/2025
Sample ID:	CCV2						
Turbidity		NTU	10.564	10	106	90-110	09/10/2025
Sample ID:	CCV3						
Turbidity		NTU	10.877	10	109	90-110	09/10/2025