

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 09/10/25 10:18 Project: Secaucus HQ Date Received: 09/10/25 Client Sample ID: 4089 SDG No.: Q3071 Lab Sample ID: Q3071-02 Matrix: Water % Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Flash Point	>212		1	0	0	o F		09/11/25 15:15	1010B
pН	6.50	Н	1	0	0	pН		09/11/25 09:30	9040C
Reactive Cyanide	0.0015	J	1	0.00096	0.0050	mg/L	09/11/25 12:30	09/12/25 10:11	9012B
Reactive Sulfide	1.00	U	1	0.43	1.00	mg/L	09/11/25 15:00	09/12/25 09:03	9034

Other method reference for flash point: Pensky-Martens Closed Cup Flash Point ASTM D 93 - IP 34, pH result reported at temperature

U = Not Detected

Comments:

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits