

Q3077-04

Lab Sample ID:

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Matrix:

SOIL

Report of Analysis

Client: PSEG Date Collected: 09/10/25 13:13

Project: Lawrenceville HQ Date Received: 09/10/25

Client Sample ID: LAW-25-0139 SDG No.: Q3077

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	5.72	Н	1	0	0	pН		09/11/25 11:40	9045D
Ignitability	NO		1	0	0	oC		09/11/25 11:25	1030
Reactive Cyanide	0.020	J	1	0.0084	0.050	mg/Kg	09/11/25 15:15	09/12/25 10:33	9012B
Reactive Sulfide	3.16	J	1	0.20	10.0	mg/Kg	09/12/25 08:45	09/12/25 13:19	9034

Comments: pH result reported at temperature 20.2 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits