

## Report of Analysis

Client:	Major Products	Date Collected:	09/11/25 11:30
Project:	Floor Drain Water 2025	Date Received:	09/11/25
Client Sample ID:	DRAIN-WATER-TANK-1	SDG No.:	Q3081
Lab Sample ID:	Q3081-01	Matrix:	WATER
		% Solid:	0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
BOD5	2960		1	0.20	2.00	mg/L		09/12/25 18:30	SM 5210 B-16
Oil and Grease	2.60	J	1	0.29	5.00	mg/L		09/15/25 10:00	1664A
pH	6.85	H	1	0	0	pH		09/15/25 08:45	9040C
TPH	0.60	J	1	0.29	5.00	mg/L		09/15/25 09:40	1664A
TSS	102		1	1.00	4.00	mg/L		09/15/25 11:00	SM 2540 D-20

Comments: pH result reported at temperature 20.1 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits