

 $284 \; Sheffield \; Street, \; Mountainside, \; New \; Jersey \; 07092, \; Phone: \; 908 \; 789 \; 8900, \\$ 

Fax: 908 789 8922

## **Report of Analysis**

Client: Core Environmental Consultants and Services, Inc. Date Collected: 08/29/25 Project: Bayshore Soil BSM Management Date Received: 08/29/25 Client Sample ID: PAULDING-WC1 SDG No.: Q3085 Lab Sample ID: Q3085-01 Matrix: **TCLP** % Solid: Level (low/med): low 0

Cas	Parameter	Conc.	Qua	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7439-92-1	Lead	36.2	J	1	11.5	60.0	ug/L	09/15/25 12:30	09/15/25 15:49	6010D	SW3050

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: TCLPMetals Group3

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits