

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Client: **ENTACT** Date Collected: 09/15/25 Project: 540 Degraw St, Brooklyn, NY - E9309 Date Received: 09/15/25 Client Sample ID: TW-WTS-14 SDG No.: Q3103 Lab Sample ID: Q3103-01 Matrix: Water % Solid: Level (low/med): low 0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-43-9	Cadmium	0.25	U	1	0.25	3.00	ug/L	09/17/25 10:32	09/18/25 13:19	6010D	SW3010
7440-50-8	Copper	2.30	U	1	2.30	10.0	ug/L	09/17/25 10:32	09/18/25 13:19	6010D	SW3010
7439-92-1	Lead	1.15	U	1	1.15	6.00	ug/L	09/17/25 10:32	09/18/25 13:19	6010D	SW3010
7439-97-6	Mercury	0.076	U	1	0.076	0.20	ug/L	09/17/25 09:20	09/17/25 14:42	7470A	
7440-02-0	Nickel	1.53	U	1	1.53	20.0	ug/L	09/17/25 10:32	09/18/25 13:19	6010D	SW3010
7440-66-6	Zinc	8.33	U	1	8.33	20.0	ug/L	09/17/25 10:32	09/18/25 13:19	6010D	SW3010

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Mercury

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits