

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: PSEG Date Collected: 09/15/25 11:41

Project: Summit Gas and Appliance Service MA00006789 Date Received: 09/15/25

Client Sample ID: SU-04-091525 SDG No.: Q3104

Lab Sample ID: Q3104-01 Matrix: SOIL

% Solid: 94.7

Parameter	Conc.	Qua.	DF MDI	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Paint Filter	1.00	U	1 1.00	1.00	ml/100gm		09/16/25 09:35	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits