

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Client: Safety Environmental Co. of NY, Inc. Date Collected: 09/18/25 Project: Kids R First Pre School 2nd Floor Trenton Date Received: 09/18/25 Client Sample ID: Fountain 1St Run SDG No.: Q3144 Lab Sample ID: Q3144-07 Matrix: Water % Solid: Level (low/med): low 0

Cas	Parameter	Conc.	Qua	. DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7439-92-1	Lead	2.62	J	1	1.21	6.00	ug/L	09/22/25 12:35	09/22/25 15:14	EPA 200.7	,

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Metals Group3

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits