

LAB CHRONICLE

OrderID: Q3144

Client: Safety Environmental Co. of NY, Inc.

Contact: Francis Owoh

OrderDate: 9/19/2025 9:37:00 AM

Project: Kids R First Pre School 2nd Floor Trenton

Location: J22

	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q3144-01	Mens Bathroom 1St Run	Water			09/18/25			09/18/25
			Metals Group3	200.7		09/22/25	09/22/25	
Q3144-02	Men Bathroom 2nd Run	Water			09/18/25			09/18/25
			Metals Group3	200.7		09/22/25	09/22/25	
Q3144-03	Classroom I 1St Run	Water		200 7	09/18/25	00/00/05	00/00/05	09/18/25
			Metals Group3	200.7		09/22/25	09/22/25	
Q3144-04	Classroom I 2nd Run	Water	Metals Group3	200.7	09/18/25	09/22/25	09/22/25	09/18/25
Q3144-05	Ladies Bathroom 1St Run	Water			09/18/25			09/18/25
			Metals Group3	200.7		09/22/25	09/22/25	
Q3144-06	Ladies Bathroom 2nd Run	Water			09/18/25			09/18/25
			Metals Group3	200.7		09/22/25	09/22/25	
Q3144-07	Fountain 1St Run	Water	Matala Cara 2	200.7	09/18/25	00/22/25	00/22/25	09/18/25
			Metals Group3	200.7		09/22/25	09/22/25	/ /
Q3144-08	Fountain 2nd Run	Water	Metals Group3	200.7	09/18/25	09/22/25	09/22/25	09/18/25
Q3144-09	Classroom 4 1St Run	Water	·		09/18/25			09/18/25
-			Metals Group3	200.7		09/22/25	09/22/25	
Q3144-10	Classroom 4 2nd Run	Water			09/18/25			09/18/25
			Metals Group3	200.7		09/22/25	09/22/25	



LAB CHRONICLE

Q3144-11	Classroom I Bathroom 1St Run	Water			09/18/25		09/18/25
	15t Ruii		Metals Group3	200.7	09/22/25	09/22/25	
Q3144-12	Classroom I Bathroom 2nd Run	Water			09/18/25		09/18/25
			Metals Group3	200.7	09/22/25	09/22/25	
Q3144-13	Classroom 2 Sink 1St Run	Water			09/18/25		09/18/25
			Metals Group3	200.7	09/22/25	09/22/25	
Q3144-14	Classroom 2 Sink 2nd Run	Water			09/18/25		09/18/25
			Metals Group3	200.7	09/22/25	09/22/25	
Q3144-15	Classroom 2 Bathroom 1St Run	Water			09/18/25		09/18/25
			Metals Group3	200.7	09/22/25	09/22/25	
Q3144-16	Classroom 2 Bathroom 2nd Run	Water			09/18/25		09/18/25
			Metals Group3	200.7	09/22/25	09/22/25	