

## Report of Analysis

Client:	PSEG	Date Collected:	09/19/25
Project:	Mechanic Street Sub Transformer Removal	Date Received:	09/19/25
Client Sample ID:	MECHANIC-ST-PAINT-CHIPS	SDG No.:	Q3146
Lab Sample ID:	Q3146-01	Matrix:	SOIL
Level (low/med):	low	% Solid:	100

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weight)	Prep Date	Date Ana.	Ana Met.	Prep Met.
7439-92-1	Lead	46600	D	5	0.56	2.61	mg/Kg	09/22/25 10:20	09/24/25 14:01	6010D	SW3050

Color Before:	Brown	Clarity Before:	Texture:	Medium
Color After:	Yellow	Clarity After:	Artifacts:	No
Comments:	Metals Group3			

U = Not Detected  
 LOQ = Limit of Quantitation  
 MDL = Method Detection Limit  
 LOD = Limit of Detection  
 D = Dilution  
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value  
 B = Analyte Found in Associated Method Blank  
 \* = indicates the duplicate analysis is not within control limits.  
 E = Indicates the reported value is estimated because of the presence of interference.  
 OR = Over Range  
 N =Spiked sample recovery not within control limits