

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: Scalamandre – Tully JV Date Collected: 09/18/25 11:30

Project: NYC DOT Harper Street Yard North Date Received: 09/19/25

Client Sample ID: MER Rd Con Ed SDG No.: Q3150

Lab Sample ID: Q3150-01 Matrix: SOIL

% Solid: 90.6

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.70	Н	1	0	0	pН		09/19/25 16:00	9045D
Ignitability	NO		1	0	0	oC		09/24/25 09:22	1030
Reactive Cyanide	0.0083	U	1	0.0083	0.050	mg/Kg	09/23/25 09:10	09/23/25 12:51	9012B
Reactive Sulfide	1.59	J	1	0.20	10.0	mg/Kg	09/23/25 11:20	09/23/25 14:05	9034

Comments: pH result reported at temperature 23.2 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits