

Report of Analysis

Client:	Scalamandre – Tully JV	Date Collected:	09/18/25 11:30
Project:	NYC DOT Harper Street Yard North	Date Received:	09/19/25
Client Sample ID:	Mid Site Grid 5-7	SDG No.:	Q3150
Lab Sample ID:	Q3150-03	Matrix:	SOIL
		% Solid:	76.7

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.42	H	1	0	0	pH		09/19/25 16:10	9045D
Ignitability	NO		1	0	0	oC		09/24/25 09:30	1030
Reactive Cyanide	0.0084	U	1	0.0084	0.050	mg/Kg	09/23/25 09:10	09/23/25 12:51	9012B
Reactive Sulfide	3.16	J	1	0.20	10.0	mg/Kg	09/23/25 11:20	09/23/25 14:08	9034

Comments: pH result reported at temperature 22.7 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits