

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Always Available Construction LLC. Date Collected: 09/19/25 13:45 Project: Date Received: Yard Soil Cleanup 09/19/25 Client Sample ID: 20-DEAD-1 SDG No.: Q3157 Lab Sample ID: Q3157-01 Matrix: SOIL % Solid: 90.9

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weigh	nt) Prep Date	Date Ana.	Ana Met.
Cyanide	0.045	U	1	0.045	0.27	mg/Kg	09/22/25 15:20	09/23/25 11:49	9012B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits