

## LAB CHRONICLE

|                                                   |                                                         |
|---------------------------------------------------|---------------------------------------------------------|
| <b>OrderID:</b> Q3157                             | <b>OrderDate:</b> 9/19/2025 2:22:59 PM                  |
| <b>Client:</b> Always Available Construction LLC. | <b>Project:</b> Yard Soil Cleanup                       |
| <b>Contact:</b> Michael Roth                      | <b>Location:</b> D31,VOA Ref. #2 Soil,VOA Ref. #3 Water |

| LabID    | ClientID  | Matrix | Test            | Method | Sample Date | Prep Date | Anal Date | Received |
|----------|-----------|--------|-----------------|--------|-------------|-----------|-----------|----------|
| Q3157-01 | 20-DEAD-1 | SOIL   |                 |        | 09/19/25    |           |           | 09/19/25 |
|          |           |        | Mercury         | 7471B  |             | 09/22/25  | 09/23/25  |          |
|          |           |        | Metals ICP-TAL  | 6010D  |             | 09/22/25  | 09/24/25  |          |
| Q3157-02 | 20-DEAD-1 | TCLP   |                 |        | 09/19/25    |           |           | 09/19/25 |
|          |           |        | TCLP ICP Metals | 6010D  |             | 09/22/25  | 09/24/25  |          |
|          |           |        | TCLP Mercury    | 7470A  |             | 09/22/25  | 09/23/25  |          |