

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Client: Weston Solutions, Inc. Date Collected: 09/23/25 12:57 Project: RFP 916 Date Received: 09/23/25 Client Sample ID: EME-TS14-02 SDG No.: Q3176 Lab Sample ID: Q3176-03 Matrix: SOIL % Solid: 70

Parameter	Conc. Qua.	DF MDL	LOQ / CRQL	Units(Dry Weight) Prep Date	Date Ana.	Ana Met.
Cyanide	0.44	1 0.058	0.34	mg/Kg 09/26/25 08:30	09/26/25 13:48	9012B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits