

## Report of Analysis

|                   |                        |                 |                |
|-------------------|------------------------|-----------------|----------------|
| Client:           | Weston Solutions, Inc. | Date Collected: | 09/23/25 12:20 |
| Project:          | RFP 916                | Date Received:  | 09/23/25       |
| Client Sample ID: | EME-TS13-01            | SDG No.:        | Q3177          |
| Lab Sample ID:    | Q3177-02               | Matrix:         | WATER          |
|                   |                        | % Solid:        | 0              |

| Parameter | Conc.  | Qua. | DF | MDL     | LOQ / CRQL | Units | Prep Date      | Date Ana.      | Ana Met. |
|-----------|--------|------|----|---------|------------|-------|----------------|----------------|----------|
| Cyanide   | 0.0014 | J    | 1  | 0.00096 | 0.0050     | mg/L  | 09/29/25 08:45 | 09/29/25 15:57 | 9012B    |

Comments: \_\_\_\_\_

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits