

В

(

SAMPLE DATA



284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

RFP 916

Report of Analysis

Client: Weston Solutions, Inc. Date Collected: 09/23/25 12:45 Project: Date Received:

Client Sample ID: EME-TS14-01 SDG No.: Q3178

Lab Sample ID: Q3178-01 Matrix: SOIL

> % Solid: 71.4

09/23/25

Parameter	Conc. Qua.	DF MDL	LOQ/CRQL U	Inits(Dry Weight	r) Prep Date	Date Ana.	Ana Met.
Cyanide	0.46	1 0.058	0.35	mg/Kg	09/26/25 08:30	09/26/25 13:48	9012B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits







LAB CHRONICLE

OrderID: Q3178

Client:

Weston Solutions, Inc.

Contact: Smita Sumbaly

OrderDate: 9/24/2025 10:59:00 AM

Project: RFP 916 Location: J33,VOA Lab

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q3178-01	EME-TS14-01	SOIL			09/23/25			09/23/25
			Cyanide	9012B	12:45	09/26/25	09/26/25	
			Cyarilde	90120		03,20,23	13.48	