

В

(

SAMPLE DATA



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Weston Solutions, Inc. Date Collected: 09/23/25 12:45

Project: RFP 916 Date Received: 09/23/25
Client Sample ID: EME-TS14-01 SDG No.: Q3179

Lab Sample ID: Q3179-01 Matrix: WATER

% Solid: 0

Parameter	Conc. Qua.	DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.0032 J	1 0.00096	0.0050	mg/L	09/29/25 08:45	09/29/25 15:57	9012B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits





LAB CHRONICLE

OrderID: Q3179

Client: Weston Solutions, Inc.
Contact: Smita Sumbaly

OrderDate: 9/24/2025 11:08:00 AM

Project: RFP 916 Location: J42

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q3179-01	EME-TS14-01	WATER			09/23/25			09/23/25
					12:45			
			SPLP Cyanide	9012B		09/29/25	09/29/25	
							15:57	