

## Report of Analysis

Client:	ENTACT	Date Collected:	09/24/25 12:00
Project:	540 Degraw St, Brooklyn, NY - E9309	Date Received:	09/24/25
Client Sample ID:	WC-A3-03-C	SDG No.:	Q3181
Lab Sample ID:	Q3181-11	Matrix:	SOIL
		% Solid:	100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	11.7	H	1	0	0	pH		09/26/25 09:00	9045D
Ignitability	NO		1	0	0	oC		09/25/25 12:10	1030
Reactive Cyanide	0.0083	U	1	0.0083	0.049	mg/Kg	09/25/25 13:30	09/26/25 11:11	9012B
Reactive Sulfide	1.58	J	1	0.20	10.0	mg/Kg	09/26/25 08:45	09/26/25 12:51	9034

Comments: pH result reported at temperature 24.7 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits