

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

## **Report of Analysis**

Client: Lockwood, Kessler & Bartlett, Inc. Date Collected: 09/23/25 12:30

Project: Syosset Landfill 2025 Date Received: 09/24/25

Client Sample ID: SY-5DL SDG No.: Q3202

Lab Sample ID: Q3202-07DL Matrix: WATER

% Solid: 0

Parameter	Conc.	Qua.	DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Chloride	203	D	100 19.0	60.0	mg/L		09/25/25 15:39	300.0

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits