

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Lockwood, Kessler & Bartlett, Inc. Date Collected: 09/23/25 Project: Syosset Landfill 2025 Date Received: 09/24/25 Client Sample ID: SDG No.: Q3202 Q3202-08 Lab Sample ID: Matrix: Water % Solid: Level (low/med): 0 low

Cas	Parameter	Conc.	Qua. DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7439-89-6	Iron	11.7	U* 1	11.7	50.0	ug/L	09/26/25 10:55	10/01/25 16:12	6010D	SW3010
7439-96-5	Manganese	75.1	1	2.97	10.0	ug/L	09/26/25 10:55	10/01/25 16:12	6010D	SW3010

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Dissolved Metals Group5

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits