

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 09/26/25 08:45 Project: Orange Gas Date Received: 09/26/25 Client Sample ID: WC-1 SDG No.: Q3231 Lab Sample ID: Q3231-04 Matrix: **SOIL** % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.60	Н	1	0	0	рН		09/30/25 09:50	9045D
Ignitability	NO		1	0	0	oC		09/30/25 15:59	1030
Reactive Cyanide	0.049	U	1	0.0083	0.049	mg/Kg	09/30/25 10:10	09/30/25 12:20	9012B
Reactive Sulfide	4.76	J	1	0.20	10.0	mg/Kg	09/30/25 14:30	09/30/25 16:29	9034

Comments: pH result reported at temperature 21.9 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits