

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

## **Report of Analysis**

Client: Yannuzzi Group, Inc. Date Collected: 09/18/25 10:31 Project: Edison Yard Date Received: 09/29/25 Client Sample ID: **RCA** SDG No.: Q3238 Lab Sample ID: Q3238-01 Matrix: SOIL % Solid: 100

| Parameter | Conc. Qu | a. I | DF MDL  | LOQ/CRQL U | Units(Dry Weigh | t) Prep Date   | Date Ana.      | Ana Met. |
|-----------|----------|------|---------|------------|-----------------|----------------|----------------|----------|
| Cyanide   | 0.10 J   | 1    | 1 0.040 | 0.24       | mg/Kg           | 09/30/25 08:00 | 09/30/25 10:53 | 9012B    |

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits