

Report of Analysis

Client: Dal-Tile - Dickson Plant
Project: Waste Water
Client Sample ID: ADDITIONAL-CYANIDE-1
Lab Sample ID: Q3258-08

Date Collected: 09/30/25 14:47
Date Received: 10/01/25
SDG No.: Q3258
Matrix: WATER
% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.0033	J	1	0.0012	0.0050	mg/L	10/14/25 08:30	10/14/25 11:18	SM 4500-CN C-21 plus E-21

Comments: _____

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N = Spiked sample recovery not within control limits