

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: ATG - AKRON LAB Date Collected: 09/30/25 00:00 Project: Date Received: PO 25061955 10/01/25 Client Sample ID: 25092166-008 SDG No.: Q3259 Lab Sample ID: Q3259-08 Matrix: SOIL % Solid: 80.3

Parameter	Conc. Qua.	DF MDL	LOQ / CRQL	Units(Dry Weight) Prep Date	Date Ana. Ana Met.	
Cyanide	0.050 U	1 0.050	0.30	mg/Kg 10/01/25 11:50	10/02/25 12:56 9012B	

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits