

## Report of Analysis

|                   |                 |                 |                |
|-------------------|-----------------|-----------------|----------------|
| Client:           | ATG - AKRON LAB | Date Collected: | 09/30/25 00:00 |
| Project:          | PO 25061955     | Date Received:  | 10/01/25       |
| Client Sample ID: | 25092166-035    | SDG No.:        | Q3259          |
| Lab Sample ID:    | Q3259-29        | Matrix:         | SOIL           |
|                   |                 | % Solid:        | 87.2           |

| Parameter | Conc. | Qua. | DF | MDL   | LOQ / CRQL | Units(Dry Weight) | Prep Date      | Date Ana.      | Ana Met. |
|-----------|-------|------|----|-------|------------|-------------------|----------------|----------------|----------|
| Cyanide   | 0.76  |      | 1  | 0.046 | 0.28       | mg/Kg             | 10/01/25 13:45 | 10/02/25 13:26 | 9012B    |

Comments: \_\_\_\_\_

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits