

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

% Solid:

100

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 10/02/25 09:48 Project: Federal Square Sub Date Received: 10/02/25 Client Sample ID: EG1-TP1 SDG No.: Q3269 Lab Sample ID: Q3269-03 Matrix: SOIL

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.50	Н	1	0	0	pН		10/02/25 15:44	9045D
Ignitability	NO		1	0	0	oC		10/06/25 08:54	1030
Reactive Cyanide	0.049	U	1	0.0083	0.049	mg/Kg	10/02/25 14:30	10/02/25 17:16	9012B
Reactive Sulfide	3.18	J	1	0.20	10.0	mg/Kg	10/03/25 08:50	10/03/25 11:08	9034

Comments: pH result reported at temperature 20.1 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits