

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: G Environmental Date Collected: 09/30/25 16:00 Project: Date Received: Newport 10/02/25 Client Sample ID: WC1 SDG No.: Q3277 Lab Sample ID: Q3277-02 Matrix: SOIL % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.22	Н	1	0	0	pН		10/03/25 16:50	9045D
Ignitability	NO		1	0	0	oC		10/06/25 09:25	1030
Reactive Cyanide	0.012	J	1	0.0083	0.049	mg/Kg	10/06/25 09:00	10/06/25 12:53	9012B
Reactive Sulfide	4.76	J	1	0.20	10.0	mg/Kg	10/03/25 08:50	10/03/25 11:13	9034

Comments: pH result reported at temperature 20.4 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits