

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 10/03/25 12:26 Project: Sewaren Laydown Yard Date Received: 10/03/25 Client Sample ID: SDG No.: Q3289 VNJ-240 Lab Sample ID: Q3289-02 Matrix: SOIL % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	6.54	Н	1	0	0	pН		10/03/25 17:10	9045D
Ignitability	NO		1	0	0	oC		10/06/25 09:40	1030
Reactive Cyanide	0.050	U	1	0.0083	0.050	mg/Kg	10/06/25 09:00	10/06/25 12:53	9012B
Reactive Sulfide	3.16	J	1	0.20	10.0	mg/Kg	10/06/25 09:15	10/06/25 11:27	9034

Comments: pH result reported at temperature 20.5 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits