

## Report of Analysis

Client: Weston Solutions, Inc.  
Project: RFP 918  
Client Sample ID: P001-DS-01  
Lab Sample ID: Q3321-01

Date Collected: 10/08/25 14:15  
Date Received: 10/09/25  
SDG No.: Q3321  
Matrix: SOIL  
% Solid: 78.4

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.99		1	0.052	0.31	mg/Kg	10/13/25 14:00	10/14/25 09:54	9012B

Comments: \_\_\_\_\_

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N = Spiked sample recovery not within control limits