

В

(

SAMPLE DATA



284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Weston Solutions, Inc. Date Collected: 10/08/25 14:15

 Project:
 RFP 918
 Date Received:
 10/09/25

 Client Sample ID:
 P001-DS-01
 SDG No.:
 Q3321

 Lab Sample ID:
 Q3321-01
 Matrix:
 SOIL

 % Solid:
 78.4



Parameter	Conc. Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.99	1	0.052	0.31	mg/Kg	10/13/25 14:00	10/14/25 09:54	9012B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits





LAB CHRONICLE

OrderID: Q3321

Client: Weston Solutions, Inc.

Contact: Smita Sumbaly

OrderDate: 10/9/2025 10:30:00 AM

Project: RFP 918

Location: D41,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q3321-01	P001-DS-01	SOIL			10/08/25			10/09/25
					14:15			
			Cyanide	9012B		10/13/25	10/14/25	
							09.54	