

LAB CHRONICLE

OrderID:	Q3323	OrderDate:	10/9/2025 2:32:00 PM
Client:	Langan Engineering and Environmental Services, Inc	Project:	Con Edison Richmond Terrace
Contact:	Gregory DelMastro	Location:	D31,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q3323-01	SED-01-0-2	SOIL			10/09/25			10/09/25
			PCB	8082A		10/13/25	10/13/25	
			Pesticide-TCL	8081B		10/13/25	10/14/25	
Q3323-02	SED-02-0-2	SOIL			10/09/25			10/09/25
			PCB	8082A		10/13/25	10/13/25	
			Pesticide-TCL	8081B		10/13/25	10/14/25	
Q3323-03	SED-03-0-2	SOIL			10/09/25			10/09/25
			PCB	8082A		10/13/25	10/13/25	
			Pesticide-TCL	8081B		10/13/25	10/14/25	
Q3323-04	SED-04-0-2	SOIL			10/09/25			10/09/25
			PCB	8082A		10/13/25	10/13/25	
			Pesticide-TCL	8081B		10/13/25	10/14/25	
Q3323-05	SED-05-0-2	SOIL			10/09/25			10/09/25
			PCB	8082A		10/13/25	10/13/25	
			Pesticide-TCL	8081B		10/13/25	10/14/25	
Q3323-06	SED-06-0-2	SOIL			10/09/25			10/09/25
			PCB	8082A		10/13/25	10/13/25	
			Pesticide-TCL	8081B		10/13/25	10/14/25	
Q3323-07	SED-07-0-2	SOIL			10/09/25			10/09/25
			PCB	8082A		10/13/25	10/13/25	
			Pesticide-TCL	8081B		10/13/25	10/14/25	