

Hit Summary Sheet
SW-846

SDG No.: Q3323

Order ID: Q3323

Client: Langan Engineering and Environmental Services.

Project ID: Con Edison Richmond Terrace

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
Client ID : SED-01-0-2								
Q3323-01	SED-01-0-2	SOIL	Aldrin	0.21	J	0.18	2.50	ug/kg
Q3323-01	SED-01-0-2	SOIL	Heptachlor epoxide	0.39	J	0.28	2.50	ug/kg
Q3323-01	SED-01-0-2	SOIL	alpha-Chlordane	0.61	JP	0.18	2.50	ug/kg
Q3323-01	SED-01-0-2	SOIL	gamma-Chlordane	0.32	J	0.22	2.50	ug/kg
Total Concentration:				1.530				
Client ID : SED-02-0-2								
Q3323-02	SED-02-0-2	SOIL	4,4-DDE	0.45	J	0.24	3.00	ug/kg
Q3323-02	SED-02-0-2	SOIL	alpha-Chlordane	0.37	J	0.21	3.00	ug/kg
Total Concentration:				0.820				
Client ID : SED-03-0-2								
Q3323-03	SED-03-0-2	SOIL	4,4-DDE	0.34	J	0.20	2.40	ug/kg
Q3323-03	SED-03-0-2	SOIL	4,4-DDD	0.71	JP	0.21	2.40	ug/kg
Total Concentration:				1.050				
Client ID : SED-07-0-2								
Q3323-07	SED-07-0-2	SOIL	4,4-DDE	0.36	J	0.17	2.10	ug/kg
Q3323-07	SED-07-0-2	SOIL	4,4-DDD	0.66	JP	0.18	2.10	ug/kg
Q3323-07	SED-07-0-2	SOIL	4,4-DDT	0.32	J	0.17	2.10	ug/kg
Q3323-07	SED-07-0-2	SOIL	alpha-Chlordane	0.71	J	0.15	2.10	ug/kg
Total Concentration:				2.050				