

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 10/14/25 Project: Waverly Substation Date Received: 10/14/25 Client Sample ID: CONCRETE-3 SDG No.: Q3340 Lab Sample ID: Q3340-07 Matrix: TCLP % Solid: Level (low/med): 0 low

Cas	Parameter	Conc.	Qua. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.	
7439-92-1	Lead	0.060	U 1 0.012	0.060	mg/L	10/15/25 12:30	10/16/25 15:25	6010D	SW3050	

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits