

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 10/16/25 10:14

Project: Trenton Gas and Appliance Service MA00006789 Date Received: 10/16/25 Client Sample ID: TR-06-101625 SDG No.: Q3366 Lab Sample ID: Matrix: SOIL Q3366-01

% Solid: 95

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Hexavalent Chromium	0.073	U	1	0.073	0.42	mg/Kg	10/20/25 11:50	10/20/25 15:10	7196A
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		10/17/25 11:15	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits