

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: PSEG Date Collected: 10/17/25 09:00

Project: Sewaren Central Maintenance Shop Date Received: 10/17/25

Client Sample ID: VNJ-255

Lab Sample ID: Q3381-08

Matrix: SOIL

% Solid: 100

Parameter Conc. Qua. DF MDL LOQ / CRQL Units **Prep Date** Date Ana. Ana Met. 6.30 0 9045D Corrosivity Η 1 0 рΗ 10/17/25 17:15 Ignitability NO 0 0 oC10/17/25 16:42 1030 Reactive Cyanide 0.050 U 1 0.00840.050 mg/Kg 10/21/25 12:24 9012B 10/20/25 14:20 Reactive Sulfide 1.59 J 1 0.20 10.0 mg/Kg 10/20/25 14:10 10/21/25 09:25 9034

Comments: pH result reported at temperature 20.1 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits