

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Yannuzzi Group, Inc. Date Collected: 09/18/25 Project: Edison Yard Date Received: 09/29/25 Client Sample ID: **RCA** SDG No.: Q3391 Lab Sample ID: Q3391-01 Matrix: Water Level (low/med): % Solid: 0 low

Cas	Parameter	Conc.	Qua.	DI	F MDL]	LOQ / CRQL	Units	P	rep Date	Date An	1a.	Ana Met.	Prep Met.
7440-48-4	Cobalt	6.57	J	1	1.13		15.0	ug/L	10/2	9/25 12:32	10/31/2	5 13:33	6010D	

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits