

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: ICE Service Group, Inc.

Project: NWIRP Northrup Grumman Site – Bethpage, NY

Client Sample ID: COMP-ROLLOFF

Lab Sample ID: Q3399-02

Date Collected: 10/20/25 12:00

100

Date Received: 10/20/25

SDG No.: Q3399 Matrix: SOIL

% Solid:

Parameter	Conc.	Qua.	DF	MDL	LOD	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	
Corrosivity	6.99	Н	1	0	0	0	pН		10/21/25 13:00	9045D	
Ignitability	NO		1	0	0	0	oC		10/22/25 09:15	1030	
Reactive Cyanide	0.025	U	1	0.0083	0.025	0.050	mg/Kg	10/21/25 08:45	10/21/25 12:39	9012B	
Reactive Sulfide	1.59	J	1	0.20	5.00	10.0	mg/Kg	10/22/25 09:20	10/22/25 13:03	9034	

Comments: pH result reported at temperature 20.1 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits