



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Initial and Continuing Calibration Verification

Client: ICE Service Group, Inc.

SDG No.: Q3399

Project: NWIRP Northrup Grumman Site – Bethpage, NY

RunNo.: LB137601

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Hexavalent Chromium	mg/L	0.495	0.5	99	90-110	10/21/2025
Sample ID: CCV1 Hexavalent Chromium	mg/L	0.496	0.5	99	90-110	10/21/2025
Sample ID: CCV2 Hexavalent Chromium	mg/L	0.491	0.5	98	90-110	10/21/2025
Sample ID: CCV3 Hexavalent Chromium	mg/L	0.496	0.5	99	90-110	10/21/2025
Sample ID: CCV4 Hexavalent Chromium	mg/L	0.489	0.5	98	90-110	10/21/2025

Initial and Continuing Calibration Verification

Client: ICE Service Group, Inc.

SDG No.: Q3399

Project: NWIRP Northrup Grumman Site – Bethpage, NY

RunNo.: LB137602

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Reactive Cyanide	mg/L	0.093	0.099	94	85-115	10/21/2025
Sample ID: CCV1 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	10/21/2025
Sample ID: CCV2 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	10/21/2025
Sample ID: CCV3 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	10/21/2025
Sample ID: CCV4 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	10/21/2025

Initial and Continuing Calibration Verification

Client: ICE Service Group, Inc.

SDG No.: Q3399

Project: NWIRP Northrup Grumman Site – Bethpage, NY

RunNo.: LB137603

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: Corrosivity	ICV	pH	6.98	7	100	90-110	10/21/2025
Sample ID: Corrosivity	CCV1	pH	2.01	2.00	101	90-110	10/21/2025
Sample ID: Corrosivity	CCV2	pH	12.02	12.00	100	90-110	10/21/2025
Sample ID: Corrosivity	CCV3	pH	2.01	2.00	101	90-110	10/21/2025

Initial and Continuing Calibration Verification

Client: ICE Service Group, Inc.

SDG No.: Q3399

Project: NWIRP Northrup Grumman Site – Bethpage, NY

RunNo.: LB137607

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID:	ICV						
pH		pH	7.00	7	100	90-110	10/22/2025
Sample ID:	CCV1						
pH		pH	2.01	2.00	101	90-110	10/22/2025
Sample ID:	CCV2						
pH		pH	12.02	12.00	100	90-110	10/22/2025

Initial and Continuing Calibration Verification

Client: ICE Service Group, Inc.

SDG No.: Q3399

Project: NWIRP Northrup Grumman Site – Bethpage, NY

RunNo.: LB137607

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
---------	-------	--------	------------	---------------	---------------------------	------------------