



SAMPLE DATA

A

B

C

Report of Analysis

Client:	ICE Service Group, Inc.	Date Collected:	10/20/25
Project:	NWIRP Northrup Grumman Site – Bethpage, NY	Date Received:	10/20/25
Client Sample ID:	COMP-ROLLOFF	SDG No.:	Q3399
Lab Sample ID:	Q3399-01	Matrix:	SOIL
Analytical Method:	8015D DRO	% Solid:	89.9
Sample Wt/Vol:	30.04 g	Final Vol:	1 mL
Prep Method:	SW3541	Prep Date	10/22/25
		Test:	Diesel Range Organics

CAS Number	Parameter	Conc.	Qua.	DF	MDL	LOD	LOQ / CRQL	Units	Date Ana.	BatchID
TARGETS										
DRO	DRO	1310	J	1	188	926	1850	ug/kg	10/22/25 14:43	PB170209
SURROGATES										
16416-32-3	Tetracosane-d50	10.5			37 - 130		52%	SPK: 20		

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit

LAB CHRONICLE

OrderID:	Q3399	OrderDate:	10/20/2025 1:23:08 PM
Client:	ICE Service Group, Inc.	Project:	NWIRP Northrup Grumman Site – Bethpage, NY
Contact:	Dennis D. Morgan, II	Location:	D41,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q3399-01	COMP-ROLLOFF	SOIL			10/20/25			10/20/25
			Diesel Range Organics	8015D		10/22/25	10/22/25	
			Gasoline Range Organics	8015D			10/21/25	
			Herbicide	8151A		10/22/25	10/23/25	
			PCB	8082A		10/22/25	10/22/25	
			Pesticide-TCL	8081B		10/22/25	10/22/25	
Q3399-02	COMP-ROLLOFF	TCLP			10/20/25			10/20/25
			TCLP Herbicide	8151A		10/22/25	10/23/25	
			TCLP Pesticide	8081B		10/22/25	10/22/25	