

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: ICE Service Group, Inc.

Project: NWIRP Northrup Grumman Site – Bethpage, NY

Client Sample ID: FRAC-TANK-0760450

Lab Sample ID: Q3400-01

Date Collected: 10/20/25 12:30

WATER

Date Received: 10/20/25 SDG No.: Q3400

% Solid: 0

Matrix:

Parameter	Conc.	Qua.	DF	MDL	LOD	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
pН	7.62	Н	1	0	0	0	рН		10/22/25 09:10	9040C
TSS	2900		1	1.00	4.00	4.00	mg/L		10/22/25 12:40	SM 2540 D-20

Comments: pH result reported at temperature 20.1 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits