

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 10/20/25 11:02

Project: Ridgefield OH Row Bridge Date Received: 10/20/25 Client Sample ID: 41-RA SDG No.: Q3402 Lab Sample ID: Matrix: SOIL Q3402-04

% Solid: 60.1

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Hexavalent Chromium	0.66	U	1	0.12	0.66	mg/Kg	10/21/25 12:00	10/21/25 16:00	7196A
Ignitability	NO		1	0	0	oC		10/21/25 12:02	1030
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		10/21/25 09:42	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits