

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: PSEG Date Collected: 10/20/25 12:10

Project:Ridgefield OH Row BridgeDate Received:10/20/25Client Sample ID:41-LBSDG No.:Q3402Lab Sample ID:Q3402-09Matrix:SOIL% Solid:100

Parameter Conc. Qua. DF MDL LOQ / CRQL Units **Prep Date** Date Ana. Ana Met. 7.27 0 9045D Corrosivity Η 1 0 рΗ 10/21/25 13:10 Ignitability NO 0 0 oC10/21/25 12:25 1030 Reactive Cyanide 0.049 U 1 0.049 mg/Kg 9012B 0.008310/21/25 08:45 10/21/25 12:47 Reactive Sulfide 1.60 J 1 0.20 10.0 mg/Kg 10/21/25 09:41 9034 10/20/25 14:10

Comments: pH result reported at temperature 20.1 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits